

Brandon Klevence - ID '14

ShopBot Part Wizard

- can draw simple shapes in wizard instead of importing Rhino vector.
 - be sure to save toolpaths if drawing in wizard
 - saved as dxf files
- preview and get acquainted with toolpaths
- be super careful, careless keystrokes can trigger shortcuts
- material Z-zero
 - set with zero plate function [**C**][2]
 - can be nudged later on if piece is not fully cut.
 - couple thousandths over top of block.

CNC Bed

- can get away w/ 18"x18" sheets min.
- use jigs for tasks that require replication.
- mount material on corresponding (by size) zone(s)
 - make sure it's square, especially if tolerances are high
 - open valve(s) for zone(s)
- use vacuum with cone attachment
 - turn on and tape if needed

Cutter

- can accomplish smaller and larger cuts depending upon cutter.
 - different chucks for S and L cutters
 - fairly sharp, handle w/ care
- always be super cautious of moving cutter in any direction, the stepper motors can generate electricity and damage the system if moved manually.
- when setting Z-zero remember to remove zero plate and clamp from cutter
- use cutter blades parallel to material edges to aid in (X,Y) zeroing
- insert cutter w/ a couple mm of stock outside of chuck

Setup, things to take note of and triple check.

- ✓ correct file
- ✓ 2D profile - default
- ✓ area clearance - raster
- ✓ machining - exact
- ✓ tool groups
- ✓ zero (X,Y,Z)
- ✓ speed of passes
- ✓ choice of cutter
 - tool database
- ✓ rotation of cutter
- ✓ cut direction
 -
- ✓ speed of spindle
- ✓ cutting inside / outside of toolpath
- ✓ plunge speed